

Error 23021: Communication to instrument failed! Please check power and connection.

Cause:

User inadvertently used Fluorescent tile during calibration instead of White ceramic tile.

Solution:

Calibrate the instrument with the correct White tile.

Author: Datacolor

Saved From: <http://knowledgebase.datacolor.com/article-565.html>