

How can I calibrate the UV content in my Spectrophotometer to measure Whiteness?

In order to accurately measure materials with optical brighteners or fluorescent colorants, the amount of UV energy emitted by the light source of the spectrophotometer must be controlled.

For step by step information on how to perform this task in Datacolor Tools refer to the attached file.

Author: Datacolor

Saved From: <http://knowledgebase.datacolor.com/article-113.html>