

Hardware Problem or No security key Found

Please check that the code key is attached to the parallel port.

In the fast computers is also related with timing. Run the SSIACT program located in DCI directory and add the line

SET SSI_ACT=x,y,z, where x, y, z are the returned values after running the SSIACT program

Author: Datacolor

Saved From: <http://knowledgebase.datacolor.com/article-31.html>