

Getting error "curtin form load - error 372 failed to load control cscomb32.ocx"

Re-install the dispenser software

Author: Datacolor

Saved From: <http://knowledgebase.datacolor.com/article-51.html>