

**I am getting Overflow error or math errors in Datacolor Tools**

Desktop is corrupted. Delete desktop and qcsetup.cnf file

Depending on the version of your software the desktop

(QC\*.DAT files) and qcsetup.cnf files are located in :

In Colortools v3.X

C:\Program Files\Datacolor\Colortools\TMP\QC\*.DAT

C:\Program Files\Datacolor\Colortools\qcsetup.cnf

In Datacolor Tools v.1.X

C:\Documents and Settings\All Users\Application Data\Datacolor\Tools\Tools\_AppUser\_XXX\QC\*.DAT where XXX is the name of your user

C:\Documents and Settings\All Users\Application Data\Datacolor\Tools\Tools\_Global\qcsetup.cnf

*Author: Datacolor*

*Saved From: <http://knowledgebase.datacolor.com/article-12.html>*