

Datacolor - Industrial Business Unit

Online Knowledgebase System

How many colors can be measured at once?

The system can measure up to 12 standard colors within a collection. \hat{A} \hat{A} System can measure unlimited number of colors outside of a collection. \hat{A} \hat{A}

Â

Â

Author: Datacolor

Saved From: http://knowledgebase.datacolor.com/article-703.html