

Datacolor - Industrial Business Unit

Online Knowledgebase System

I am experiencing instrument calibration or communication problems

Exit all applications

Delete file c:Paintmkrspectro (this is a spectro file in paintmaker NOT THE SPECTRO DIRECTORY)

Restart windows

Reload instrument drivers and calibration data

Author: Datacolor

Saved From: http://knowledgebase.datacolor.com/article-11.html