

How do I remove the gray background on the printout of reflectance plots in Datacolor Tools?

Datacolor Tools doesn't have an option to modify this setting. It is suggested to change the preferences of your printer. The attached document shows an example of changing some printer settings to remove the gray background. Your printer may not have these exact settings, or may be under a different heading.

Author: Datacolor

Saved From: <http://knowledgebase.datacolor.com/article-597.html>