

The calculation of OperTotTime does not work properly. It doesn't calculate the time for heating or cooling.

ITMProcess uses the unit defined in ITMRegistry to recognise heating or cooling units. Check that the unit selected in ITMRegistry | System setting | Prod units still exists.

Author: Datacolor

Saved From: <http://knowledgebase.datacolor.com/article-82.html>