

Some dyelots appear twice in SmartWeigh.

The ITMProcess user has created a dyelot with a space at the end of the dyelot ID. A corrective add is done in SmartWeigh. After this you will find two dyelots in the database. One with a space at the end, the second without.

Solution:

Avoid spaces in IDâ€™s.

Author: Datacolor

Saved From: <http://knowledgebase.datacolor.com/article-94.html>